

FIELD ENGINEERING SUPPORT SOUTHBORO

Technical Information Bulletin

TIB

DATE: 1-9-73
FROM: L. BRONISZ
SUBJECT: INSTRUCTION TIMER DIAGNOSTICS

NUMBER: S1001
CATEGORY: PROCESSORS
MODEL: ALL

PROBLEM: The various instruction timer diagnostics for all processors will not run properly with the Cassette I/O board in the system.

SOLUTION: Because of the very small number of problems discovered by the instruction diagnostic, it has been decided not to revise the diagnostic. These diagnostics are being removed from the document package that the customer will receive. The diagnostic will be kept for in-plant use and will be available to field service.

DISTRIBUTION

A, E, F, G, I