

FIELD ENGINEERING SUPPORT SOUTHBORO

*Technical Information Bulletin*

**TIB**

DATE: 25 JUNE 1973  
FROM: A. BELANGER  
SUBJECT: HOLDING SCREWS ON  
BACKPANEL CAPACITORS

NUMBER: S1004  
CATEGORY: POWER SUPPLIES  
MODEL: 2054, 2048, 2046,  
2041, 8281, 2039,  
8181

EARLY SYSTEMS USED AN ALLEN SCREW FOR MOUNTING CAPACITORS WHICH WAS NOT LONG ENOUGH TO HOLD PROPERLY.

THIS RESULTS IN THE CAP PULLING LOOSE AND ARCING TO THE ETCH. THIS COULD CAUSE A VARIETY OF MALFUNCTIONS.

ALLEN SCREW PART NO. 106-000-347 SHOULD BE USED AS A REPLACEMENT. THIS ALLEN IS LONG ENOUGH TO ALLOW IT TO BE THREADED TO THE BOTTOM OF THE CAP AND STILL BE LONG ENOUGH FOR MOUNTING ALL STAND-OFFS AND HARDWARE.

DISTRIBUTION

A, E, F, G, I