

FIELD ENGINEERING SUPPORT SOUTHBORO

Technical Information Bulletin

TIB

DATE:	20 NOVEMBER 1975	NUMBER:	S1013
FROM:	DONNIE REED	CATEGORY:	POWER SUPPLIES
SUBJECT:	-5 VOLT OUTPUT LESS THAN -4 VOLTS	MODEL:	1210

ECO 2454 changed the -5 Volt choke from 18 to 12 turns to correct an overvoltage condition. In some systems, this change may cause the -5 volt output to drop below -4 volts. To correct this situation, change CR3 from a 1N4001 (P/N 101-175) to a 1N4934 (P/N 101-148). Reference ECO 3849 and drawing 001-172.

DISTRIBUTION

A, B, D, F, G, I